


Current level relay



① Power light: shine when the product is power on

② Overcurrent indication Operation light

③ Ie setting knob

④ Hysteresis value setting knob

⑤ Time delay adjusting knob

$$\text{Reset current} = (1 - \text{Hys}) \times I_e$$

252mm